



Vehicle identification number (VIN)	WPOZZZ97ZHL11
Order type	Panamera 4 E-Hybrid (97ABE1)
Model year	2017

Collapse all

Campaigns



There are no campaigns for this vehicle.

Warranty data

Description	From	To	Contract ...	Coverage	Assistance	Mileage limit (km)	
Corrosion warranty	07/07/2020	07/07/2029	07/07/2017		No	-	
New vehicle warranty	07/07/2017	07/07/2025	07/07/2017	> PAG High-Vol...	No	160000	
New vehicle warranty	07/07/2017	07/08/2027	07/07/2017	Connect compens...	No	-	
Expired warranties 7							<input checked="" type="checkbox"/> Show
Pre-owned warranty	07/07/2023	03/06/2024	06/28/2023		No	-	
Pre-owned warranty	07/07/2022	07/06/2023	07/04/2022		No	-	
Pre-owned warranty	07/07/2021	07/06/2022	06/15/2021		No	-	
Pre-owned warranty	07/07/2020	07/06/2021	05/15/2019		Yes	-	
New vehicle warranty	07/09/2019	01/07/2021	07/07/2017	> PAG High-Vol...	No	120024	
New vehicle warranty	07/07/2017	07/06/2020	07/07/2017		Yes	-	
New vehicle warranty	07/07/2017	01/07/2021	07/07/2017	> PAG High-Vol...	No	160000	



Vehicle identification number (VIN)	WPOZZZ97ZHL115
Order type	Panamera 4 E-Hybrid (97ABE1)
Model year	2017

Annotation: The information listed below might not be a complete vehicle history. Only jobs that have been documented within PCSS job management (PQIS) are available. This information may not be transmitted to third parties.

Total warranty repair days (WRD): **61 Day(s)**

Filter settings

- Workshop/Recall ...
- OTA campaign
- Repair
- Maintenance/Insp...
- Documentation

Reset Filter

Collapse all

Status	Repair Start	Repair End	Dealer	Mileage	DMS order number	
DMS	04/18/2024	04/19/2024	9212078	46221 mls	062240	1
Repair			Location: 10010 Engine Symptom: 2021 Clanks, whirs			
DMS	03/22/2024	03/22/2024	9212041	46432 mls	19327	2
Documentation			Warranty check for pre-owned Porsche vehicles: 111 used car chek			
Documentation			Other: wheel alignment			
DMS	06/16/2023	06/26/2023	9212001	42299 mls	26435	6
Campaign			Location: Campaign complete: WMJ52 Affixing indication sticker on the charger (OBC) Symptom: 6600 Workshop campaign			
Campaign			Location: Campaign complete: WPF81 Re-programming instrument cluster Symptom: 6600 Workshop campaign			
Documentation			corrosion warranty check: LLG Report			
Documentation			Technical inspection §: MOT			
Maintenance/Inspection			Minor maintenance: Minor service including Pollen filter, Spark plugs, Transmission oil & filter change, Air filter & BFC			
Repair			Location: 19780 Temperature sender Symptom: 5011 Water leaks			
DMS	02/16/2022	02/18/2022	9212001	30232 mls	61123	4
Campaign			Location: Campaign complete: WMJ61 Re-program and/or code seat control unit Symptom: 6600 Workshop campaign			
Repair			Location: 19380 Coolant Symptom: 9734 Customer complaint cannot be reproduced			
Repair			Location: 55370 Filler flap Symptom: 1712 Catches/hangs			
Repair			Location: 10010 Engine Symptom: 9734 Customer complaint cannot be reproduced			
DMS	06/15/2021	06/18/2021	9212001	25944 mls	50856	2
Documentation			Technical inspection §: MOT			

Documentation		Technical inspection s: MUI
Maintenance/Inspection		Major maintenance: Major service including Pollen filter & BFC

DMS 03/29/2021 03/31/2021 9212001 25338 mls 48483 4

Campaign			Location: Campaign complete: WLD42 Replace positive crankcase ventilation hose Symptom: 6600 Workshop campaign
Campaign			Location: Campaign complete: WLG01 Re-program DME control unit Symptom: 6600 Workshop campaign
Repair			Location: 55370 Filler flap Symptom: 1712 Catches/hangs
Repair			Location: 55400 Side section flap Symptom: 1111 Adjustment fault

DMS 10/30/2019 12/06/2019 9212001 19400 mls 35057 7

Campaign			Location: Campaign complete: WKK21 Re-program RDK control unit Symptom: 6600 Workshop campaign
Campaign			Location: Campaign complete: AKB81 Re-programming instrument cluster Symptom: 9900 Recall campaign
Campaign			Location: Campaign complete: WKH61 Re-coding service interval Symptom: 6600 Workshop campaign
Campaign			Location: Campaign complete: WKJ01 Re-programming air-conditioning control unit Symptom: 6600 Workshop campaign
Repair			Location: 55380 Filler flap switching element Symptom: 1613 No function occasionally
Repair			Location: 44400 Tire Symptom: 1041 Foreign objects
Repair			Location: 27910 Power electronics Symptom: 5011 Water leaks

DMS 04/29/2019 05/01/2019 9212020 13948 mls 19879 5

Campaign			Location: Campaign complete: WJ701 Fill in refrigerant oil for refrigerant circuit Symptom: 6600 Workshop campaign
Campaign			Location: Campaign complete: AKA11 Re-programming instrument cluster Symptom: 9900 Recall campaign
Campaign			Location: Campaign complete: WJ831 Pedal feel Symptom: 6600 Workshop campaign
Documentation			Warranty check for pre-owned Porsche vehicles: 111 point check
Maintenance/Inspection			Minor maintenance: Intermediate maintenance & brake fluid change

01/17/2019 01/17/2019 9212001 12008 mls 3

Campaign			Location: Campaign complete: AJ131 Re-programming control unit for electric power steering Symptom: 9900 Recall campaign
----------	--	--	--

Campaign			Symptom: 7700 Recall campaign
			Location: Campaign complete: WJ612 Check filler flap / charge port door and replace if necessary Symptom: 6600 Workshop campaign
Repair			Location: 96620 Handheld transmitter Symptom: 9734 Customer complaint cannot be reproduced

10/11/2018 10/11/2018 9212001 9907 mls 6

Campaign			Location: Campaign complete: WJ051 Re-code front camera control unit Symptom: 6600 Workshop campaign
Campaign			Location: Campaign complete: WJ271 EFP control unit Symptom: 6600 Workshop campaign
Campaign			Location: Campaign complete: WH321 Reworking cooling fan housing Symptom: 6600 Workshop campaign
Campaign			Location: Campaign complete: WJ151 Re-program control unit for high-voltage charger Symptom: 6600 Workshop campaign
Campaign			Location: Campaign complete: WJ671 Re-program DME and PDK control unit Symptom: 6600 Workshop campaign
Maintenance/Inspection			Engine oil change: Oil change

01/29/2018 01/29/2018 9212001 4424 mls 1

Repair			Location: 90250 Instrument cluster Symptom: 4041 Incorrect display
--------	--	--	---

09/28/2017 09/28/2017 9212020 1690 mls 58069 3

Campaign			Location: Campaign complete: WH301 Re-programming the airbag control unit Symptom: 6600 Workshop campaign
Campaign			Location: Campaign complete: WH311 Send Driver's Manual Supplement Symptom: 6600 Workshop campaign
Documentation			Warranty check for pre-owned Porsche vehicles: Carry out 111 point check

07/12/2017 07/12/2017 9212020 17 km 56040 1

Documentation			General workshop visit / Service (DMS)
---------------	--	--	--

07/04/2017 07/04/2017 9212020 17 mls 55164 1

Repair			Location: 03350 On board diagnostic Symptom: 1100 Adjustment fault
--------	--	--	---